

2018 BOND IMPROVEMENTS*



Ralston Valley Articulation Area

	Build new facility on same property	Expand with addition	Remodel building interior	Additions/renovations for programs	Growth accommodations	Remove modular buildings	Security camera & lock updates	Secure entries & office locations	New, more secure exterior doors	More secure & energy-efficient windows	Update existing technology	Landscaping & field improvements	Update interior paint, wall-coverings	Update electrical wiring & increase capacity	Update HVAC, plumbing & piping	Repair & update caulk, trim & window sills	New paint to protect exterior	Commercial kitchen improvements	Parking lot & sidewalk improvements	Replace old playground equipment	Replace old furniture	Replace old carpet & floor tile	Replace movable partitions	Replace old sinks, cabinets & shelving	Replace interior lighting with LEDs	Replace worn roofing
Coal Creek Canyon K-8							•	•		•	•			•	•					•		•			•	
Meiklejohn Elementary							•	•		•			•												•	
Oberon Middle		•	•				•	•	•	•	•		•	•									•	•	•	
Ralston Valley High		•	•	•			•	•		•	•		•	•										•		
Sierra Elementary																										
Three Creek K-8		•									•															
Van Arsdale Elementary						•	•	•		•			•	•						•	•	•			•	
West Woods Elementary							•	•		•		•								•	•	•			•	

*Based on 2018 Capital Improvement Plan. Subject to project scope.

Van Arsdale Elementary School Improvements

- Update security cameras & classroom security door hardware.
- Secure building vestibules, entries & office location.
- Update existing technology for student learning.
- Remove modular buildings.
- Update old electrical wiring, panels & increase capacity.
- Update old heating & cooling equipment, plumbing fixtures & piping.
- Replace:
 - Old playground equipment;
 - Old library furniture;
 - Interior lighting with energy-efficient LEDs; &
 - Old carpet & floor tile.



Age of Facility: 24 years (built in 1994)
Square Footage: 50,512

Enrollment: 507

**BUILDING
CONDITION:
POOR**

FCI: 33.9%

FCI is a measurement of the physical condition of the school's interior, exterior & grounds.

Good: less than 10%
Fair: 11% to 30%
Poor: greater than 30%.

Estimated cost of proposed improvements: \$3,773,128. Subject to change per final project scope.